

[Next Unread Message](#)[View Message](#)

Sent on 08 06 2015 Expires on 08 21 2015
From Motorcycle National Field Service
Subject UPDATE: SAFETY RECALL - Starter Relay Switch Inspection/Replacement



Motorcycle National Field Service

REVISED August 6, 2015

UPDATE: SAFETY RECALL - Starter Relay Switch Inspection/Replacement

Dear Honda Powersports Dealer:

Reminder

Many of the units affected by this recall can be sold if they pass the inspection procedure. Inspect all affected units in your inventory immediately. Please follow the steps below to ensure that your dealership does not miss any sales opportunities or incur any recall sell-through violations.

Inspect Affected Units ASAP

1. Identify affected units in your inventory by using *eResponsibility Report* on *IN*.
(To search for applicable recalls on a specific unit, use *Unit Information* on *IN*.)
2. Inspect the affected unit according to the procedure in the *Service Bulletin*.
 - a. If the unit has an OK starter relay switch, apply the appropriate punch mark as indicated in the Service Bulletin and immediately submit the warranty claim to avoid a recall sell-through violation.
 - b. OK units are eligible for retail sale. Immediately Sales Register the unit when it is sold.
 - c. If the starter relay switch is within the "No Good" lot number range, set the unit aside until replacement parts arrive.

NOTE: If you have repaired an affected unit with a part from another vehicle, apply the appropriate punch mark and file a warranty claim (on the affected unit only) as indicated in the Service Bulletin.

Urgent Administrative Notice

In order to determine unit eligibility for flooring credit, please continue to inspect and repair units as outlined in Service Bulletin *Multi-Model: Starter Relay Switch #1* and immediately file the appropriate warranty claim.

Parts Information

An initial limited allocation of repair parts, based upon your dealership's affected inventory and sold units, began shipping on July 30. Repair Parts will be available on open order when parts supplies are sufficient to repair all dealer and customer units.

Sincerely,

American Honda Motor Co., Inc.

Bradley LittleManager, National Field Service
Motorcycle Division

Bulletin Number: 15-0215

 [**BACK TO TOP**](#)

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.