

[Next Unread Message](#)[View Message](#)

Sent on 08 17 2015 Expires on 08 26 2015
From Motorcycle National Field Service
Subject RECALL INFORMATION UPDATE: Starter Relay Switch #1



Motorcycle National Field Service

August 17, 2015

Recall Information Update: Starter Relay Switch #1

Dear Honda Powersports Dealer:

PARTS INFORMATION

- An initial limited allocation of "MR5" parts shipped on July 30.
- An initial limited allocation of "MT4" parts will ship Monday, August 17.
- The next shipment of both part numbers is planned for the end of August.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters the week of August 24, 2015 based on vehicle registration information.

REVISED SERVICE BULLETIN

The Service Bulletin (*Multi-Model: Starter Relay Switch #1*) has been revised as follows:

- Contrary to the initial information, VT750CS and VT750C2S are not affected by this recall.
- Many units have been factory inspected/tested and have OK starter relay switches. See the revised Service Bulletin for details.

Sincerely,
American Honda Motor Co., Inc.

Bradley Little
Manager, National Field Service
Motorcycle Division

Bulletin Number: 15-0236

 [**BACK TO TOP**](#)

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.