

Publish Date: August 13, 2015  
From: Technical Service  
Expiration Date: August 27, 2015

DCSnet  
Message  
Urgent

Subject: **Recall 15V- xxx: Front Parking Lights Inoperative after Programming**

**Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians**

**Message Text:**

Due to a programming software error in ISTA/P 3.56.1 or higher, both front "parking lights" no longer work when the parking lights or when the headlights are switched on (F30/F31 produced up to June 31, 2015). Therefore, the affected vehicles no longer conform to applicable regulation. BMW Group is conducting a voluntary non-compliance recall 15V-xxx to correct this problem. Please refer to B63 07 15 (attached) for repair solution and further information. Please contact your field representatives if you have any questions.

Sincerely, Eugene Aton, Technical Service

Attachments: [B630715\[81551525\].pdf](#)  
[B630715\\_Safety\\_Recall\\_Notice\[81551524\].pdf](#)

Recipients: BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, All Departments, All Personnel  
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel