

SAFETY RECALL ALERT



To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Bulletin: SRA-M-0392
Date: August 18, 2015
Action Required? **YES**

From: Regulatory Affairs Department

Subject: Safety Recall, SC0392, Brake Caliper

Summary:

Description of Defect:

The brake chambers may have been incorrectly mounted on certain trucks with Meritor Air Disc Brakes. This can result in internal contamination of the air disc brake caliper, which may result in loss of brakes at the wheel end.

Mack Trucks has received no reports of crashes or personal injury as a result of this condition. Therefore, Mack considers this as a proactive measure to protect the public and Mack's customers from the potential risk associated with this defect.

Models/ Model Years Affected:

Mack: Certain 2013-2015 Mack Pinnacle (CXU) model trucks manufactured with Meritor Air Disc Brakes from October 3, 2012 through February 18, 2014

Vehicle Quantities:

Mack: 79 Trucks all U.S.

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle will be posted on the Trucks Dealer Portal August 18, 2015.
- Repair Instructions are tentatively scheduled for release no later than September 21, 2015.
- Owner Notices are scheduled to be mailed on or before September 21, 2015.

Questions:

Contact the Regulatory Affairs Department at ytna.regulatoryaffairs@volvo.com if you have questions.