



Michael A. Berardi  
 Director  
 Service Engineering Operations  
 Ford Customer Service Division

Ford Motor Company  
 P. O. Box 1904  
 Dearborn, Michigan 48121

October 15, 2015

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: DEMONSTRATION / DELIVERY HOLD - Safety Recall 15S25**  
 Certain 2016 Model Year F-53 and F-59 Vehicles  
 Transmission Shift Cable Bracket Replacement

**AFFECTED VEHICLES**

Vehicle	Model Year	Assembly Plant	Build Dates
F-53 Motorhome	2016	Detroit Chassis Plant	June 1, 2015 through August 11, 2015
F-59 Stripped Chassis			

Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS SAFETY RECALL**

In the affected vehicles, the transmission shift cable bracket may have been manufactured out of specification, causing the transmission shift cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the gear shift lever when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash.

**SERVICE ACTION**

Dealers are to replace the transmission shift cable bracket and adjust the shift cable. This service must be performed on all affected vehicles at no charge to the vehicle owner.

**OWNER NOTIFICATION MAILING SCHEDULE**

Owner Letters are expected to be mailed the week of November 9, 2015. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

**PLEASE NOTE:**

**Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.**

**ATTACHMENTS**

Attachment I: Administrative Information  
 Attachment II: Labor Allowances and Parts Ordering Information  
 Attachment III: Technical Information  
 Owner Notification Letter

**QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,



Michael A. Berardi