



File Attachment Information

File Size (MB)	File Name	
0.06	D-Mail R57.pdf	
0.06	D-Mail R58.pdf	
0.06	D-Mail R59.pdf	
0.06	D-Mail R60.pdf	
0.06	D-Mail R61.pdf	~





10/16/2015

New Safety Recall Advanced Communication – R61101615

FCA US LLC announced a safety recall on certain 2012 through 2015 model year (JC) Dodge Journey vehicles equipped with an Anti-lock Brake System (ABS).

Some of the above vehicles may have a ground wire eyelet on the right front shock tower that allows water to wick through the ground wire case and into the ABS module. Moisture in the ABS module could disable the ABS and/or Electronic Stability Control (ESC) system(s). The lack of a functioning ABS and/or ESC system(s) could change the braking and/or handling characteristics of the vehicle and cause a crash without warning.

FCA will conduct a voluntary safety recall on all involved vehicles. The ground eyelet on the right shock tower must be sealed to stop water migration through the ground wire case. The ABS module and headlamp/dash wire harness must also be inspected for moisture and repaired and/or replaced if required.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations FCA US LLC