



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

January 2017

This notice applies to your vehicle: XXXXXXXXXXXXXXXXXXXX

RE: 2015–16 Fit
NHTSA Recall 15V-697

IMPORTANT

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear :

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. Certain 2015–16 Honda Fit vehicles fail to conform to Federal Motor Vehicle Safety Standard No. FMVSS 214 “Side Impact Protection” and FMVSS 226 “Ejection Mitigation”, and the risk of injury is increased. In the event of a collision, the rear grab rail brackets may interfere with the side curtain airbag deployment, increasing the risk of injury to the outboard seat occupants.

What will Honda do?

Honda will replace your vehicle’s rear grab rail brackets **free of charge**. Call any authorized Honda dealer and make an appointment to have your vehicle repaired.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #15-079

JV8