

[Next Unread Message](#)[View Message](#)

|         |                                           |    |      |            |    |    |      |
|---------|-------------------------------------------|----|------|------------|----|----|------|
| Sent on | 01                                        | 22 | 2016 | Expires on | 02 | 05 | 2016 |
| From    | Motorcycle National Field Service         |    |      |            |    |    |      |
| Subject | RECALL INFORMATION UPDATE: S/B GL1800 #23 |    |      |            |    |    |      |

Re: Service Bulletin GL1800 #23 - 2001-2015 GL1800/A, GL1800B/BD Secondary Master Cylinder Replacement

Dear Honda Powersports Dealer:

The available stock of the repair kit for '13-'14 GL1800B/BD (F6B) has become low. As a result, the availability of P/N 06454-MJG-306 will be controlled by TechLine until further notice. All other parts for this campaign remain available on open order.

- If your Service Dept. has a scheduled recall repair appointment for '13-'14 GL1800B/BD (F6B), contact TechLine immediately to secure a repair kit.
- If your Sales Department has a pending sale of a new or used '13-'14 GL1800B/BD (F6B), contact TechLine immediately to secure a repair kit and then perform the recall repair before selling the motorcycle.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine at (800) 421-1900, Option 9; through TechLine Connect on iN; or contact your District Service Manager.

Sincerely,  
American Honda Motor Co., Inc.

Bradley Little  
Manager, National Field Service  
Motorcycle Division

Bulletin Number: 16-0018