

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4182  
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 1, 2016

Subject: 15757C – Safety Recall  
Under Hood Fire  
Revised Service Procedure section

Models: 1997-2004 Buick Regal  
2000-2004 Chevrolet Impala  
1998-1999 Chevrolet Lumina  
1998-2004 Chevrolet Monte Carlo  
1998-1999 Oldsmobile Intrigue  
1997-2004 Pontiac Grand Prix  
Equipped with 3.8L V6 engine (RPO L26, L32, L36 or L67)

To: All General Motors Dealers

This bulletin is being revised to enhance the Service Procedure with additional information to assure proper sealing of the replacement valve cover gasket. Please discard all copies of bulletin 15757B.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS