



Michael A. Berardi
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 27, 2015

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: DEMONSTRATION / DELIVERY HOLD Advance Notice - Compliance Recall
15C13**
Certain 2016 Model Year Mustang Vehicles
Restraint Component Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Mustang	2016	Flat Rock	September 26, 2015 through October 2, 2015

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS COMPLIANCE RECALL

Some of the affected vehicles may not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 209, Seat belt assemblies or FMVSS No. 225, Child restraint anchorage systems. The affected parts may include: Left-Hand (LH) and Right-Hand (RH) front seatbelt retractors and pretensioners, LH and RH rear seatbelt retractors, LH and RH rear seatbelt buckles, and LH and RH rear child safety seat tether anchors. These parts may have sustained damage prior to installation that could affect performance, increasing the risk of an injury in a crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any of the affected vehicles involved in this compliance recall. A complete Dealer Bulletin will be provided to dealers by the week of November 30, 2015, when it is anticipated that parts ordering information and repair instructions will be available to support this compliance recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael A. Berardi". The signature is fluid and cursive, with a prominent initial "M" and a long, sweeping underline.

Michael A. Berardi