

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Recall 15V-xxx: Front Passenger Seat Cushion with Capacitive Interior Sensing (CIS) Mat
Date: Thursday, November 05, 2015 4:34:14 PM

Publish Date: November 05, 2015
From: Technical Service
Expiration Date: November 19, 2015

DCSnet Message
Urgent



Subject: Recall 15V-xxx: Front Passenger Seat Cushion with Capacitive Interior Sensing (CIS) Mat

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

BMW AG is conducting a Voluntary Safety Recall involving the Front Passenger Seat Cushion including CIS Mat Sensor – **prior parts replacement:**

- Model Year 2014-2015 MINI Cooper and Cooper S Hardtop 2 Door (F56)
- Model Year 2014-2015 MINI Cooper and Cooper S Hardtop 4 Door (F55)

These vehicles may have received an incorrectly programmed seat mat sensor during front passenger seat cushion **replacement by a MINI Dealer (prior repair)**. For additional details, Service Information M65 12 15, Q&A and Legal Recall notice are attached.

Sincerely, Eugene Aton, Technical Service

Attachments:

-  [Recall Notice M651215\[815ddd26\].pdf](#)
-  [M651215\[815ddd25\].pdf](#)
-  [B651215_QA\[815ddd24\].pdf](#)
-  [Recall Notice M651215\[815ddd26\].pdf](#)
-  [M651215\[815ddd25\].pdf](#)
-  [B651215_QA\[815ddd24\].pdf](#)

Recipients: MINI Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel