



## **SUBJECT**

### **Recall 15V-xxx: Front Passenger Seat Cushion with Capacitive Interior Sensing (CIS) Mat – Prior Parts Replacement**

## **MODEL**

F56 (Hardtop 2-door)

F55 (Hardtop 4-door)

## **SITUATION**

BMW AG is conducting a Voluntary Safety Recall involving the Front Passenger Seat Cushion including CIS Mat Sensor – prior parts replacement:

- Model Year 2014-2015 MINI Cooper and Cooper S Hardtop 2 Door (F56)
- Model Year 2014-2015 MINI Cooper and Cooper S Hardtop 4 Door (F55)

These vehicles may have received an incorrectly programmed seat mat sensor during front passenger seat cushion replacement by a MINI Dealer (prior repair).

For your reference, a Q&A has been attached.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.