



## **SUBJECT**

### **Delivery Stop – Checking Driveshaft Universal Joint**

## **MODEL**

F80 (M3 Sedan)  
F82 (M4 Coupe)  
F83 (M4 Convertible)

## **SITUATION**

A Delivery Stop has been issued on F80, F82 and F83 vehicles produced from May 30, 2015 to October 11, 2015. These vehicles will require a Driveshaft Universal Joint inspection and possible replacement. There are only **eight** vehicles affected by this stop. For your convenience, attached you will find the list of affected VINs.

This bulletin will be updated with repair instructions and warranty information when it becomes available.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

**“A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin B26 01 15.”**