



12/23/2015

New Safety Recall Advanced Communication – R68122315

FCA announced a safety recall on certain 2015 model year (MK) Jeep Compass and Jeep Patriot vehicles.

Some of the above vehicles may have a power steering hose clamp that was not installed correctly during the manufacturing process. The low pressure power steering return hose may detach and cause a large volume power steering fluid leak. Leaking power steering fluid, in contact with an ignition source, could result in an engine compartment fire without warning.

FCA will conduct a voluntary safety recall to inspect the power steering return hose clamp for proper installation and reposition the clamp if required.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC