

Ferrari North America, Inc.

December 18, 2016

Dear Ferrari Dealer:



Ferrari has decided that in addition to the Model Year 2016 California T vehicles that we have already communicated to you, certain **Model Year 2016 Ferrari 488 vehicles** may also have a defect in a Low Pressure Fuel Line Connection, which may cause a fuel evaporation leak during engine start, and possibly lead to smoke or a fire. We want to assure you that our clients' safety is our priority, and we are committed to correcting this condition in their vehicle.

The vehicle may have been fitted with a defective Low Pressure Fuel Line provided by the supplier. This manufacturing defect is due to an improper coating treatment made by the supplier on the metallic connection of the Low Pressure Fuel Line where it connects to the Fuel Pump. Failure to have this defect remedied could lead to smoke or fire if the potential fuel evaporation leak into the engine compartment occurs.

The affected vehicles consist of **Model Year 2016 Ferrari 488 vehicles** with a VIN range from ZFF79ALA0G0214237 to ZFF79ALAXG0215427.

Ferrari will repair the vehicle free of charge. The repair involves replacing the Low Pressure Fuel Line. This repair takes approximately 2 hours to complete.

Please be advised that as of the date of this letter, no unremedied vehicles have been sold to retail customers.

It is a violation of Federal law for a dealer to deliver a new motor vehicle covered by this notification under a sale or lease until the defect is remedied.

Upon transmittal of the repair under the normal warranty system, we will of course reimburse you for the parts and labor necessary to carry out this campaign.

Technical Department
Ferrari North America, Inc.