



SUBJECT

Recall 15V-xxx: DSC Hydraulic Unit System

MODEL

I12 (i8)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving Dynamic Stability Control (DSC) Hydraulic Unit System in certain i8 (I12). Approximately 16 vehicles may be affected.

Due to a supplier error in the manufacturing process, the drill holes of one or more of the six pump pistons may not have been produced to specification. As a result, this could cause one or more pistons to become restricted. If this occurred, it could lead to impairment of the DSC functions, including the braking function. As a result, vehicle handling and control could be affected, increasing the risk of a crash.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.