



Mercedes-Benz

**IMPORTANT SAFETY RECALL 2015030005**

**This notice applies to your vehicle,  
WDDLJ9BB6EA113598  
Tail Lamp Side Markers  
NHTSA Recall # 15V137**

Mercedes-Benz USA, LLC

Gareth Joyce

Vice President  
Customer Services

April, 2015



Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has decided that in certain Model Year 2012 - 2015 CLS – Class vehicles the rear tail lamp side markers may fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, reflective devices and associated equipment." Our records indicate that your vehicle is included in the potentially affected population of vehicles.

**WE SENT YOU THIS NOTICE BECAUSE WE ARE CONCERNED ABOUT YOUR SAFETY.**

DAG has determined that the level of illumination of the rear tail lamp side markers in your vehicle might be below the required level permitted by FMVSS 108 due to a software coding issue which leads to the non-activation of certain LEDs. Insufficient illumination levels of the rear tail lamp side markers may reduce the vehicles visibility and could increase the risk of a crash. To correct this condition an authorized Mercedes-Benz dealer will update the software coding for the tail lamp side markers.

**This service will be provided free of charge.** We are dedicated to always delivering the Best or Nothing – and respect for your time is a top priority. While the minimum repair time is approximately one half hour, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

For additional information and to schedule an appointment please contact **MERCEDES-BENZ OF CALDWELL, 973-227-3600** or another authorized dealer, at your earliest convenience. To locate additional authorized dealers see [www.MBUSA.com/dealerlocator](http://www.MBUSA.com/dealerlocator). **Please mention you are scheduling an appointment to update the tail lamp side markers software coding under Recall Campaign # 2015030005.** You may be asked for your 17-digit Vehicle Identification Number (VIN) which, for your convenience, is located above your name at the top of this letter.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

Should you have any questions or encounter any difficulty regarding this Recall Campaign please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372). A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, now offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See [www.MBUSA.com/recall](http://www.MBUSA.com/recall).

If an authorized Mercedes-Benz dealer or MBUSA fails or is unable to perform this service without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this situation may cause you.

Sincerely,



Mercedes-Benz – are registered trademarks of Daimler AG, Stuttgart, Germany

Mercedes-Benz USA, LLC  
One Mercedes Drive  
P.O. Box 350  
Montvale, NJ 07645-0350  
Phone 1-800-FOR-MERCEDES (1-800-367-6372)  
Fax (201) 476-6211  
[www.MBUSA.com](http://www.MBUSA.com)

IMPORTANT

IF FOR ANY REASON YOU DO NOT NOW OWN THIS VEHICLE OR HAVE A CHANGE OF ADDRESS, PLEASE COMPLETE THE SECTION BELOW, PLACE IN THE ENCLOSED ENVELOPE, AND DROP IN ANY MAIL BOX. IF POSSIBLE, PROVIDE THE NAME AND ADDRESS OF THE PRESENT OWNER SO THAT WE MAY CONTACT THEM.

☐ SCRAPPED

☐ STOLEN

☐ OTHER \_\_\_\_\_

☐ SOLD

I HAVE SOLD THE VEHICLE TO: \_\_\_\_\_

☐ MY NEW ADDRESS IS: \_\_\_\_\_

NAME \_\_\_\_\_

STREET \_\_\_\_\_

APT. \_\_\_\_\_

CITY \_\_\_\_\_

STATE \_\_\_\_\_

ZIP \_\_\_\_\_

PHONE \_\_\_\_\_

THANK YOU FOR YOUR COOPERATION



Mercedes-Benz

Mercedes-Benz USA, LLC

P.O. Box 301

Broadway, NJ 08808-0301

Presorted  
First Class Mail  
U.S. Postage Paid  
New Brunswick, NJ  
Permit # 1

# SAFETY RECALL NOTICE


## IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance  
With Federal Law



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES



## BUSINESS REPLY MAIL

FIRST-CLASS MAIL

PERMIT NO. 37

MONTVALE NJ

POSTAGE WILL BE PAID BY ADDRESSEE

ATTN: CUSTOMER ADVOCACY  
CUSTOMER ASSISTANCE CENTER  
MERCEDES-BENZ USA LLC  
PO BOX 350  
MONTVALE NJ 07645-9978

