



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

December 16, 2015

IMPORTANT SAFETY RECALL

Subject: Safety Recall 15KWP - Fontaine Ultra LT 5th Wheel
NHTSA Recall number 15V-641
This notice applies to your vehicle; 1XKFD49X2BJ290071

C & R EXPRESS, INC.
660 EVENHOUSE ROAD
LAKE ALFRED FL 33850

Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain 2011 model year T700's built from 9/21/2010 through 10/1/2010 with Fontaine Ultra LT Fifth Wheel connectors. The defect involves a susceptibility of the fifth wheel and its locking mechanism to cumulative damage that may cause the fifth wheel lock to function improperly or a failure of the locking mechanism to properly engage.

If the fifth wheel and locking mechanism are sufficiently damaged, the locking mechanism may fail to operate as intended and the trailer may unexpectedly detach from the tractor, increasing the risk of crash.

<i>The problem is...</i>	Damaged fifth wheel or locking mechanism on Fontaine Ultra LT Fifth Wheel
<i>What your dealer will do...</i>	Dealers will replace the fifth wheel top plate
<i>What you must do ...</i>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to replace the fifth wheel top plate with locking mechanism. This repair should take approximately **3.0 Hours** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Director, Customer Service



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

December 16, 2015

IMPORTANT SAFETY RECALL

Subject: Safety Recall 15KWP - Fontaine Ultra LT 5th Wheel
NHTSA Recall number 15V-641
This notice applies to your vehicle; The VINS are listed on the back of this letter

MAY TRUCKING
4185 BROOKLAKE RD NE
SALEM OR 97303-9729

Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain 2011 model year T700's built from 9/21/2010 through 10/1/2010 with Fontaine Ultra LT Fifth Wheel connectors. The defect involves a susceptibility of the fifth wheel and its locking mechanism to cumulative damage that may cause the fifth wheel lock to function improperly or a failure of the locking mechanism to properly engage.

If the fifth wheel and locking mechanism are sufficiently damaged, the locking mechanism may fail to operate as intended and the trailer may unexpectedly detach from the tractor, increasing the risk of crash.

<i>The problem is...</i>	Damaged fifth wheel or locking mechanism on Fontaine Ultra LT Fifth Wheel
<i>What your dealer will do...</i>	Dealers will replace the fifth wheel top plate
<i>What you must do ...</i>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to replace the fifth wheel top plate with locking mechanism. This repair should take approximately **3.0 Hours** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Director, Customer Service

(Over Please)

Affected VINS:

1XKFD48X7BJ291864

1XKFD48X9BJ291865

1XKFD48X0BJ291866

1XKFD48X2BJ291867

1XKFD48X4BJ291868

1XKFD48X6BJ291869

1XKFD48X2BJ291870

1XKFD48X4BJ291871

1XKFD48X6BJ291872

1XKFD48X8BJ291873