



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 15E-085

November 23, 2015

MAILED

NOV 23 2015

NAVISTAR INC.attn: Gary Wagner
2701 Navistar Dr.
Lisle IL 60532

Compliance Dept.

Dear Cummins Westport Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cummins Inc. and Cummins Westport Inc. have decided that a defect which relates to motor vehicle safety exists in certain Cummins Westport ISL G engines built from September 13, 2007 through September 23, 2015. Your engine is being recalled to address this condition.

This notice applies to your Cummins Westport engine as identified below:

Engine Serial Number	Vehicle Manufacturer	Vehicle Serial Number
73503566	Navistar	1HSHWCVN7EJ492381
73504329	Navistar	1HSHWCVN7EJ492400
73573926	Navistar	1HSHXCVR3EH492403

WHY IS A RECALL BEING CONDUCTED?

The turbocharger oil supply line may make contact or interfere with other engine or vehicle components. If this occurs, the resulting contact or interference may damage the turbocharger oil supply line, possibly resulting in an oil leak near the exhaust manifold. This condition may result in a fire.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Campaign C1673 "ISL G Low Mount Turbo Oil Supply Line Safety Campaign" to correct this condition. Engines will be inspected for interference with and/or damage to the turbocharger oil supply line. If necessary, changes will be made to eliminate the interference and, if necessary, the turbocharger oil supply line will be replaced. This campaign is currently available at Cummins Distributors and Cummins-authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 45 minutes to complete.

WHAT SHOULD YOU DO?

Contact the nearest Cummins Distributor or Cummins-authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair.