



565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

May 26, 2015

Can-Am® Spyder® RT™ 2013 - Updated Maintenance Schedule - Operator's Guide Label

Dear Can-Am Spyder owner,

You are receiving this decal along with the Safety Recall Notice letter - Can-Am Spyder Roadster RT 2013 – Elevated Temperature in Engine Compartment.

This updated maintenance schedule will take effect when your vehicle has been repaired as per the above described safety recall notice.

EVERY 46 000 KM (28,500 MI)
Replace the rear sprocket bearing.
Replace the canister pre-filter (if so equipped).

In the Operator's guide **Maintenance Schedule**, affix the provided label over the existing 46 000 KM (28,500 MI) maintenance specification.

We apologize for any inconvenience this situation may have caused.

Sincerely,
After-Sales Service Department

Ski-Doo
Lynx
Sea-Doo
Evinrude
Rotax
Can-Am