



Dear Indian Motorcycle Scout Owner:

Safety and quality are the highest priority for Indian Motorcycle, and we want to make you aware of an important safety concern for model year 2015 Scout bikes.

We have issued a safety recall for all Scout bikes (I-15-01) pertaining to a Rear Master Cylinder issue. We recently discovered that our supplier provided a portion of a rear brake master cylinder that does not meet Indian Motorcycle quality standards. To ensure that we continue to deliver world class quality and address this potential hazard, Indian Motorcycle dealers will inspect and, if necessary, replace the rear brake master cylinder assembly.

Formal Safety Bulletins for this concern have been delivered to dealers. Service parts will be available for dealers to order immediately to ensure any needed repairs can be made as soon as possible. Indian Motorcycle will replace all parts and make necessary repairs at no cost to customers.

We apologize for the inconvenience caused by this announcement as we work together to ensure safe riding.

Thank you for your continued support.

The Indian Motorcycle Team