



SLINGSHOT

Slingshot Safety Recall Notification

Dear Slingshot Owner,

Safety and quality are the highest priority for Polaris. We want to make you aware of an important safety concern affecting model year 2015 and 2016 Slingshot vehicles.

We have issued a Safety Recall for some Slingshot vehicles (SLI-15-05) pertaining to a potential issue in the headlight wiring circuit. In some vehicles, heat buildup in the engine compartment may cause the headlight circuit relay to derate below the required current draw of the headlights. In addition, temperatures produced at the fuse box terminal pin may be higher than desired. The result of such a condition could be a loss of forward lighting function. This could cause decreased visibility for the vehicle operator, increasing the risk of a vehicle crash.

To ensure that Slingshot continues to deliver world class quality and address this potential hazard, we will install a headlight jumper harness on all affected vehicles. Polaris will replace all parts and make necessary repairs at no cost to you.

A formal Safety Bulletin for this concern has been delivered to dealers, and service parts are currently available for dealers to order. Please contact your local dealer to schedule your service work at your earliest convenience.

We apologize for the inconvenience caused by this announcement as we work together to ensure safe riding.

Thank you for your continued support.

The Slingshot Team