

Reference	SSM72200
Models	Range Rover / L322
Title	P054 Front Brake Hose Replacement LR048085
Category	Chassis
Last modified	20-Mar-2015 00:00:00
Symptom	301000 Service Brake System
Attachments	existing brake line buffer and fixing.jpg (existing brake line buffer and fixing.jpg) new brake line with existing fixing that will not latch.jpg (new brake line with existing fixing that will not latch.jpg)

ContentIssue:

When replacing the front brake hose associated with Recall P054 (part number LR048085) on Range Rover (L322) vehicles 2006 to 2012 model years, the combination wiring harness/brake hose fixing clip (part # SGK000110) will not latch around the round rubber buffer of the replacement brake hose.

Cause:

The rubber buffer on the new replacement brake hose is of a larger outside diameter and will not allow the circular portion of the existing retaining clip to latch (see photo illustration).

Action:

Transfer the existing correct diameter buffer from the old brake hose to the new hose in the following manner.

Remove the rubber buffer from the original brake hose by cutting the buffer fully through with a sharp blade from top to bottom. Cleanse the existing buffer before transfer to the new hose. .

Carefully displace the buffer on the new hose by sliding it down the hose approximately 10 mm to make room for the buffer from the original hose to reside. Fit the original rubber buffer in its place. Rejoin the previously cut buffer using a suitable glue.

Caution ! Do not attempt to remove or modify the rubber buffer on the new brake hose as damage to the new hose may occur.

Secure clip SGK000110 as normal.

This issue is currently under investigation and a new brake hose part number with correctly sized rubber buffer will be released in due course.