

Reference:

ITB13-018g

Date:

June 15, 2017

**VOLUNTARY SAFETY RECALL CAMPAIGN
2003 FX, 2001 I30, 2002-2003 I35, 2002-2003 QX4;
FRONT PASSENGER AIR BAG INFLATOR**

CAMPAIGN ID #: R1303 / R1406
NHTSA #: 15V-287
APPLIED VEHICLES: 2003 FX (S50)
2001 I30 (CA33)
2002 – 2003 I35 (CA33)
2002 – 2003 QX4 (JR50)

This bulletin has been superseded as follows:

2003 FX (S50); superseded by ITB17-022

2001 I30 (CA33); superseded by ITB17-038

2002 – 2003 I35 (CA33); superseded by ITB17-038

2002 – 2003 QX4 (JR50); superseded by ITB17-021

Please discard previous versions of this bulletin.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.