
June 5, 2015

01979 Version 2

Safety Recall: RLX Sport Hybrid CMBS Error

This bulletin is replaced by S/B 15-030, *Safety Recall: RLX and RLX Sport Hybrid CMBS Error*.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.