



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

June 2017

RE: 2002-2006 CR-V
NHTSA Recall 15V-320

IMPORTANT

- **Your vehicle is included in a safety recall and you should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear JOHN Q SAMPLE:

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle, refer to the address card for the affected VIN. In certain 2002-2006 Honda CR-V vehicles, the driver side front airbag inflator could produce excessive internal pressure upon deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator to rupture (break apart). In the event of an inflator rupture, metal fragments could pass through the airbag cushion material possibly causing serious injury or fatality to you or others in the vehicle. Past ruptures like this have injured or killed vehicle drivers.

What will Honda do?

Honda will replace your vehicle's driver side front airbag inflator **free of charge**. Call any authorized Honda dealer and make an appointment to have your vehicle repaired.

What if I have additional questions?

If you have any questions about this notice, or you need assistance locating a dealer, contact the Honda Customer Support & Campaign Center at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

American Honda Motor Co., Inc.

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #15-040

JR1

0626-02-00-00000004-0002-00000009