



# IMPORTANT: SAFETY RECALL REMINDER

In August 2015, we notified you of a Safety Recall involving the starter relay switch on your 2013-2016 Honda motorcycle or scooter. At the time, we advised owner's of the following:

**During assembly of the starter magnetic switch, it is possible the sealant may have been applied incorrectly. Incorrectly applied sealant may cause an interruption of the electrical system which may cause the engine to A) not start or B) stall while riding. The increased resistance at the main fuse could cause the starter relay switch to catch on fire.**

According to our records, you have not yet had your affected motorcycle/scooter repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If you have already had your motorcycle/scooter repaired, or if you no longer own this motorcycle/scooter, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,  
American Honda Motor Co., Inc.  
Motorcycle Division

MTB 15631 (1510)



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES



**BUSINESS REPLY MAIL**  
FIRST-CLASS MAIL PERMIT NO. 247 PLYMOUTH, MI

POSTAGE WILL BE PAID BY ADDRESSEE



AMERICAN HONDA MOTOR CO INC  
47911 HALYARD DRIVE  
PLYMOUTH MI 48170-9935