

August 9, 2016

SECOND NOTICE IMPORTANT SAFETY RECALL

**This notice applies to your vehicle
VINs are listed on the back of this page.**

Subject: Safety Recall 1115P Michelin Tires MN295/60R22.5 XZA2 18 Ply
NHTSA # 15V-740
EXPIRATION DATE: NONE

USA Customer
99 Customer Address
SOMETOWN, USA

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2009 through 2016 Peterbilt vehicles manufactured from January 19, 2008 through October 12, 2015 and built with Michelin XZA2 295/60/R22.5 front tires in auto hauler applications. Trucks with these front tires and a GAWR rated greater than 14,300lbs may have had the vehicle speed programmed greater than 65mph (104kph). Also, trucks with these front tires and a GAWR rated less than 14,300lbs may have had the vehicle speed programmed greater than 75mph (120kph). Maximizing the front axle load in these trucks may cause the tires to become overloaded when the vehicle is operated in excess of the tire's speed rating.

An overloaded and/or over-spiced tire may experience premature wear or failure, which may increase the possibility of a crash.

<i>The problem is...</i>	Engine vehicle speed may exceed speed rating of front tire for associated GAWR
<i>Correction...</i>	Dealers will reprogram the maximum vehicle speed to appropriate setting for GAWR
<i>What you must do ...</i>	Regularly inspect tires for wear, ensure proper tire inflation at all times, limit vehicle speed in accordance with the published speed rating of the front tire for your GAWR, and contact your dealer to schedule an appointment

Peterbilt will remedy the defect free of charge by reprogramming the maximum vehicle speed. The free remedy will be available starting January 29, 2016. Please contact a Peterbilt dealership to schedule this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take approximately 0.50 hour labor. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Douglas K. Gunter

Doug Gunter
Director of Warranty
Peterbilt Motors Company