



IC Bus, LLC
2701 Navistar Drive
Lisle, IL 60532 USA

navistar.com

MAILED
MAY 18 2015
Compliance Dept.

**IMPORTANT SAFETY RECALL INTERIM
NOTICE 15504**

MAY 2015

Dear IC Bus Customer,

This notice applies to your vehicle identified on the enclosed card. This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that a defect which relates to motor vehicle safety exists in certain 2015 CE commercial bus models built on 1 October 2014 with feature code 04EVK or 04EXM Haldex Life Seal rear brake chambers.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

Navistar requests your patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

IC Bus, LLC

REASON FOR THIS RECALL

A diaphragm in the Haldex spring brake chamber may not be seated fully into the pressure plate and may cause internal leakage in the chamber resulting in the parking brake to not fully release and drag.

RISK TO MOTOR VEHICLE SAFETY

Parking brakes that drag, or may not fully release, could potentially overheat and result in a wheel end fire which may cause property damage or personal injury.

ACTIONS YOU SHOULD TAKE

A final remedy has been determined. Repair parts have been ordered and will be available in mid-June. When parts become available, you will be notified of additional actions you should take.

During the interim period, should your truck experience parking brakes to not fully release or drag, bring your truck to the nearest International® dealer for repair.

You can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.internationaltrucks.com>.