

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** 15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)  
**Date:** Tuesday, August 23, 2016 11:39:34 AM

Publish Date: August 23, 2016  
From: Parts Logistics  
Expiration Date: September 06, 2016

DCSnet Message  
**Important**



**Subject: 15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)**

**To:** All BMW Parts and Service Managers

**Re:** 15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)

The first batch of Customer Letters for E46, E39 and E53 final repair were mailed last week. This mailing involves customer vehicles that are currently or were ever registered in High Absolute Humidity areas such as Alabama, California, Florida, Georgia, Guam, Hawaii, Louisiana, Mississippi, Puerto Rico, Samoa, Texas, US Virgin Islands, Saipan and South Carolina as per the NHTSA requirements.

With the limited supply of parts available, we began accepting email request for those customer VINs which contain the final repair defect code 00 32 39 02 00.

**Please submit one VIN per email request to [specialpartsrequest@bmwna.com](mailto:specialpartsrequest@bmwna.com) including the following information:**

Subject Line: 15V-318 SIB 65 11 15  
Dealer Location Code:  
Part Number:  
VIN Number:

Orders will be placed on your behalf using the VIN+AB as the PO (i.e.VX12345AB). **Please ensure these air bag modules are used on the VIN specified in the PO only.**

We will provide an update when the next batch of customer letters are mailed.

Thank you,  
Parts Logistics

**Attachments:**  
No Attachments No Attachments

**Recipients:** BMW Passenger Cars, CC-All  
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All  
BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, All

