



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 21, 2016

Brent Roy
Compliance
Autocar Industries, LLC
551 S Washington Street
Hagerstown, IN 47362

NEF-150MR
16V-319

Subject: Wheel Separation from Rear Axle

Dear Brent Roy:

This letter serves to acknowledge Autocar Industries, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AUTOCAR/XPERT/2017
AUTOCAR/XSPOTTER/2016-2017

Mfr's Report Date: May 17, 2016

NHTSA Campaign Number: 16V-319

Components:

SUSPENSION:REAR:AXLE:SPINDLE

Potential Number of Units Affected: 43

Problem Description:

Autocar Industries, LLC (Autocar) is recalling certain model year 2016-2017 Auto Xspotter and 2017 Autocar Xpert vehicles manufactured March 04, 2016, through April 21, 2016. The tab lock washers on the rear axle wheel ends may not have been properly bent over the outer spindle nut during assembly.

Consequence:

If the spindle nuts loosen, the wheel assembly may separate from the rear axle, increasing the risk of a crash.

Remedy:

Autocar will notify owners and dealers will inspect the tab lock washers and remedy tabs where needed, free of charge. The recall is expected to begin on June 30, 2016. Owners may contact Autocar's customer service at 1-765-489-5499. Autocar's number for this recall is MDTT-1601.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Autocar's proposed owner notification letter and its currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement