



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 14, 2016

Mr. R. Thomas Brunner
Dept Manager VCA
Mercedes-Benz USA, LLC.
1 Mercedes Drive
Montvale, NJ 07645

NEF-150TB
16V-442

Subject: Right Rear Seat Belt Anchorage Bolt Misinstalled

Dear Mr. Brunner:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/ML250/2015
MERCEDES BENZ/ML350/2015
MERCEDES BENZ/ML400/2015
MERCEDES BENZ/ML63/2015
MERCEDES-BENZ/GLE450/2016

Mfr's Report Date: June 13, 2016

NHTSA Campaign Number: 16V-442

Components:

SEAT BELTS:REAR

Potential Number of Units Affected: 423

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2015 ML250, ML350, ML350 4Matic, ML400 4Matic, ML63 AMG, and 2016 GLE450 AMG 4Matic vehicles manufactured from April 27, 2015, through May 19, 2015. The affected vehicles may have had the right rear seatbelt anchor bolt incorrectly installed.

Consequence:

In the event of a vehicle crash, the right rear seatbelt anchor bolt could fail to secure the passenger, increasing their risk of injury.

Remedy:

MBUSA will notify owners, and dealers will inspect and, if necessary, correct the installation of the right rear seat belt anchor bolt, free of charge. The recall is expected to begin in July 2016. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received MBUSA's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Timian", with a horizontal line extending to the right.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement