



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

January 3, 2017

Mr. R. Thomas Brunner
Dept Manager VCA
Mercedes-Benz USA, LLC.
1 Mercedes Drive
Montvale, NJ 07645

NEF-150TB
16V-901

Subject: Brake Booster Vacuum Line Connector May Break

Dear Mr. Brunner:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/CLA250/2014

Mfr's Report Date: December 12, 2016

NHTSA Campaign Number: 16V-901

Components:

SERVICE BRAKES, HYDRAULIC:POWER ASSIST:VACUUM:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 10

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2014 CLA250 vehicles manufactured December 14, 2012, to April 24, 2013 equipped with gasoline engines. The affected vehicles have a fitting that connects the vacuum line to the brake booster which may break causing increased forced to be needed to apply the brakes.

Consequence:

If the vehicles unexpectedly need increased pressure on the brake pedal to apply the brakes, there would be an increased risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will replace the connector end fitting at the brake booster, free of charge. The recall is expected to begin in February 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement