

**Recall Quarterly Report****16V-024**

**Manufacturer Name :** Rosenbauer Motors  
**NHTSA Recall No. / MFR Recall No. :** 16V-024 /TSB 01-009-15  
**Recall Subject :** Ball Joints may Detach from Front Suspension  
**Owner Notification Beginning Date :** SEP 02, 2015  
**Owner Notification End Date:** SEP 02, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	FEB 03, 2016	2015-3	9	9	0	0

This Document Last Updated : FEB 03, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.