

**Recall Quarterly Report****16V-163****Manufacturer Name :** Triumph Motorcycles America, LTD**NHTSA Recall No. / MFR Recall No. :** 16V-163 /**Recall Subject :** Fuel may Leak into Fuel Pump Harness**Owner Notification Beginning Date :** APR 08, 2016**Owner Notification End Date:** APR 29, 2016

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 21, 2016	2016-3	120	88	0	0
1	OCT 21, 2016	2016-2	120	82	0	0

This Document Last Updated : OCT 21, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.