

**Recall Quarterly Report****16V-203**

**Manufacturer Name :** Mazda North American Operations  
**NHTSA Recall No. / MFR Recall No. :** 16V-203 /9316D  
**Recall Subject :** Insufficient Bolt Torque may Cause Steering Loss  
**Owner Notification Beginning Date :** MAY 10, 2016  
**Owner Notification End Date:** MAY 10, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JUL 28, 2017	2017-2	578	441	3	0
4	APR 28, 2017	2017-1	578	426	3	0
3	JAN 30, 2017	2016-4	578	401	0	0
2	OCT 30, 2016	2016-3	578	354	0	0
1	JUL 27, 2016	2016-2	578	348	0	0

This Document Last Updated : AUG 02, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.