

Recall Quarterly Report**16V-371**

Manufacturer Name : Terex Advance Mixer, Inc.
NHTSA Recall No. / MFR Recall No. : 16V-371 /
Recall Subject : Driveshaft may Disconnect
Owner Notification Beginning Date : JUL 15, 2016
Owner Notification End Date: JUL 15, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 24, 2017	2017-3	117	10	0	0
4	JUL 20, 2017	2017-2	117	10	0	0
3	JAN 30, 2017	2017-1	117	10	0	0
2	JAN 30, 2017	2016-4	117	10	0	0
1	OCT 24, 2016	2016-3	117	10	0	0

This Document Last Updated : OCT 24, 2017

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.