

Recall Quarterly Report**16V-694**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 16V-694 /WTK-71
Recall Subject : Windshield Wiper Motor Bottom Cover may Melt
Owner Notification Beginning Date : OCT 25, 2016
Owner Notification End Date: OCT 25, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 14, 2017	2017-2	592,647	357,926	9,689	0
2	APR 12, 2017	2017-1	592,647	317,259	0	0
1	JAN 23, 2017	2016-4	592,647	247,682	0	0

This Document Last Updated : JUL 24, 2017

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.