

Recall Quarterly Report**16V-806**

Manufacturer Name : Terex Advance Mixer, Inc.
NHTSA Recall No. / MFR Recall No. : 16V-806 /
Recall Subject : King Pin Fracture may cause Wheel End Separation
Owner Notification Beginning Date : JAN 05, 2017
Owner Notification End Date: JAN 05, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 30, 2017	2017-1	19	0	0	0

This Document Last Updated : JAN 30, 2017

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.