

**Part 573 Safety Recall Report****16V-058****Manufacturer Name :** Highland Ridge RV**Submission Date :** JAN 29, 2016**NHTSA Recall No. :** 16V-058**Manufacturer Recall No. :** 9904277**Manufacturer Information :**

Manufacturer Name : Highland Ridge RV

Address : 955 Tuscany Drive

Shipshewana IN 46565

Company phone : 260-768-7771

**Population :**

Number of potentially involved : 239

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2016 Travel Trailers multiple

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2015-2016 Highlander models HT27SBB,HT31RGR

2015-2016 Mesa Ridge models MR337RLS,MR340FLR

2015-2016 Roamer models RT337RLS, RT340FLR

2015-2016 Journeyer models JT337RLS, JT340FLR

Production Dates : APR 07, 2014 - JAN 11, 2016

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Safety chains placed on the A-frame by supplier are rated for 11,700lb and are not in compliance with safety chain rating per industry SAE - which states that each safety chain must be equal or greater than the GVWR of the travel trailer.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Weight of the trailer may break weaker chain and pull the travel trailer away from tow vehicle - causing accident and personal injury

Description of the Cause : Error made on Highland engineering print provided to supplier

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

January 22 2016 was reported that during annual maintenance of NTA documents, it was discovered that certain models of travel trailers had a GVWR that exceeded the industry SAE rating on the safety chains supplier had on the A-frame. Supplier was conducted immediately and prints were reviewed and found to be in error (Highland's error) calling out a 11,700 lb safety chain when the correct should be 16,200lb safety chain. Correct prints are now on file with the supplier 1-25-16 changes were made on the production line with supplier arriving on 1-26 to repair all units on site that required the heavier chains

**Description of Remedy :**

Description of Remedy Program : Highland Dealers will remove the existing safety chains replacing wit 16,200 lb rated safety chains

How Remedy Component Differs from Recalled Component : size

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported