

Part 573 Safety Recall Report**16V-062**

Manufacturer Name : Forest River, Inc.
Submission Date : JAN 31, 2016
NHTSA Recall No. : 16V-062
Manufacturer Recall No. : 37-01152016-0131

**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.
 Address : 55470 CR 1
 P.O. Box 3030 Elkhart IN 46515-3030
 Company phone : 1-800-348-7440

Population :

Number of potentially involved : 12
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Forest River, Inc. Surveyor - SVF275BHSS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Surveyor SVF275BHSS is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : NOV 04, 2015 - NOV 11, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4FSVD24GL027895

End : 4X4FSVD20GL027960

Not sequential VINs

Description of Defect :

Description of the Defect : Some of the electrical wiring was incorrectly manufactured by the Surveyor manufacturing facility the parts were installed on a limited number of vehicles with model number SVF275BHSS. The General Circuit Receptacles are incorrectly wired with two incoming hot wires and should only have one hot wire, a neutral wire, and a ground wire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : With two incoming hot wires, the receptacle may receive "over-current," which could cause an electrical arc and potentially electrocute the user.

Description of the Cause : The General Circuit Receptacles are incorrectly wired with two incoming hot wires and should only have one hot wire, a neutral wire, and a ground wire.

Identification of Any Warning that can Occur : The General Receptacle Breaker in the Converter/Invertor (panel box) will trip, cutting power to the General Receptacle Circuit.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On January 15, Surveyor Quality Control identified the defect with the 110 volt General Circuit and notified the Surveyor Warranty Manager, who in turn informed the Office of Corporate Compliance. Forest River initiated an internal investigation at that time. On January 27, 2016 the Corporate Recall Committee met and approved the recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide any parts, wiring, breakers and any other items needed to remedy the described defect, free of charge to any dealer to remedy for the owner.

What is the Forest River Customer Service Phone Number? (574) 642-3119
Ext. 205

How Remedy Component Differs from Recalled Component : The General Circuit is now checked by wired with a single hot, neutral, and ground wire to the receptacle that can be identified through the main converter box.

Identify How/When Recall Condition was Corrected in Production : On January 15, 2016, Surveyor notified the Forest River Office of Corporate Compliance of an issue affecting the General Circuit. According to Surveyor, the issue has been corrected in production, and the General Circuit has been wired so that the receptacles have a single hot, neutral, and ground wire.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAR 29, 2016 - MAR 29, 2016

Planned Owner Notification Date : MAR 29, 2016 - MAR 29, 2016

* NR - Not Reported