

Part 573 Safety Recall Report**16V-082****Manufacturer Name :** Starcraft RV**Submission Date :** FEB 11, 2016**NHTSA Recall No. :** 16V-082**Manufacturer Recall No. :** 9902282**Manufacturer Information :**

Manufacturer Name : Starcraft RV

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 800-945-4787

Population :

Number of potentially involved : 5

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Fifth Wheels 3 as noted

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : G2HD5063 364 RKTS SOLSTICE FW
 G2HE5052 377 RDN SOLSTICE FW
 G2KP5062 287RLS TRAVEL STAR FW
 G2KP5067 305 RLT TRAVEL STAR RW
 G2HD5066 364 RKTS SOLSTICE

Production Dates : JUL 31, 2015 - SEP 14, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Per Atwood Recall 15E-087 - Atwood found that the water flow adjustment feature on the On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3gal/min or less.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Per Atwood, if this adjustment setting is allowed to drift to, or has been set at , .3 gal/minute or less, the condition of concern can occur and n lead to a scald injury to the user.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Atwood Mobile Products

Address : 1120 N Mian Street

Elkhart INDIANA 46514

Country : United States

Chronology :

12-18-15 Atwood provided a list of 5 serial numbers of their on demand water heaters involved in their recall 15E087 - Corp Engineering ran data queries to locate what units were built with the recalled water heaters.. NONE were found. 2-9-16 while researching a customer complaint , it was discovered that production records on file were in error, calling out the wrong model of Atwood water heater. Information was corrected immediately, and Corp Engineering then ran another query to try and find the 5 recalled Atwood water heaters... With the corrected models noted, all five have been located and we are moving forward to contact the current owners... of the 5 only 3 are in units residing in US.. with the balance of 2 in Canada.

Description of Remedy :

Description of Remedy Program : Per Atwood, qualified service center - Installation of a water flow adjustment stop key that prevents the adjustment of the water flow down below .5gal/min. the addition of a star or lock washer to secure the adjustment screw that prevents unintended adjustment or and adjustment drift from vibration when trailer is in motion. - Warning and tamper proof label applied over the stop key and adjustment screw.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Starcraft will notify current owners with instructions to contact Atwood for the recall remedy.

Planned Dealer Notification Date : FEB 17, 2016 - FEB 17, 2016

Planned Owner Notification Date : FEB 17, 2016 - FEB 17, 2016

* NR - Not Reported