

Part 573 Safety Recall Report**16V-089****Manufacturer Name :** Keystone RV Company**Submission Date :** FEB 16, 2016**NHTSA Recall No. :** 16V-089**Manufacturer Recall No. :** 16-247**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000

2642 Hackberry Drive Goshen IN 46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 107

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Keystone Sprinter

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Units manufactured with Haier 55" TV

Production Dates : JUL 28, 2015 - NOV 19, 2015

VIN (Vehicle Identification Number) Range

Begin : 4YDF35327G1531256

End : 4YDF35320G1532068

 Not sequential VINs**Description of Defect :**

Description of the Defect : It has been decided the vehicles in this recall population may have been manufactured with a Haier 55" Model 55E2500 TV that can break off of the wall mounting inside the vehicle. Reference 16E011.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the TV breaks loose from the wall while person is nearby, it will lead to an increased risk of personal injury.

Description of the Cause : The TV does not have necessary backing to provide the lower installation screws with a secure connection.

Identification of Any Warning that can Occur : The TV may be loose or partially separated from the mounting bracket.

Supplier Identification :**Component Manufacturer**

Name : Haier America

Address : 1800 Valley Road

Wayne NEW JERSEY 07470

Country : United States

Chronology :

January 25, 2016 – Keystone was contacted by Midwest Sales to have the TV's replaced. An investigation into the cause and scope of the problem was initiated.

February 12, 2016 - The investigation was completed and a recall was initiated to replace the subject TV's.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the TV.

How Remedy Component Differs from Recalled Component : The replacement TV is a 55" Sansui SLED5515

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : FEB 22, 2016 - FEB 22, 2016

Planned Owner Notification Date : FEB 22, 2016 - FEB 22, 2016

* NR - Not Reported