

**Part 573 Safety Recall Report****16V-168****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** MAR 22, 2016**NHTSA Recall No. :** 16V-168**Manufacturer Recall No. :** S16**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)  
 Address : 800 Chrysler Drive  
 CIMS 482-00-91 Auburn Hills MI 48326-2757  
 Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 14,768  
 Estimated percentage with defect : 1

**Vehicle Information :**

Vehicle : 2015-2016 Jeep Grand Cherokee

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Some 2015-2016 MY Jeep Grand Cherokee ("WK") vehicles.

Production Dates : DEC 09, 2015 - JAN 14, 2016

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2016 Dodge Durango

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Some 2015-2016 MY Dodge Durango ("WD") vehicles.

Production Dates : DEC 09, 2015 - JAN 14, 2016

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The left front brake caliper may be cast from an incorrect material which may crack under an extreme braking application.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This condition may result in an increased stopping distance.

Description of the Cause : NR

Identification of Any Warning that can Occur : The vehicle operator may notice brake fluid leakage, illumination of a low brake fluid light, and reduced brake performance.

**Supplier Identification :**

**Component Manufacturer**

Name : Mobis North America

Address : 6401 W. Fort St.

Detroit MICHIGAN 48209

Country : United States

**Chronology :**

Please see the attached supplemental information titled "FCA US LLC Chronology WD WK – Grey Iron Caliper – 03222016.pdf".

**Description of Remedy :**

Description of Remedy Program : Conduct a Voluntary Safety Recall on all affected vehicles to inspect the front left caliper date code and replace the caliper if it is from the suspect casting date.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : FCA US will provide a dealer notification and owner notification schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported