

Part 573 Safety Recall Report**16V-298****Manufacturer Name :** Supreme Corporation**Submission Date :** MAY 10, 2016**NHTSA Recall No. :** 16V-298**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Supreme Corporation

Address : 2581 East Kercher Road
Goshen IN 46528

Company phone : 999

Population :

Number of potentially involved : 80

Estimated percentage with defect : NR

Vehicle Information :

Vehicle : 2010-2016 Supreme Classic American Trolley

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Driver Seatbelt

Production Dates : NOV 19, 2010 - JAN 29, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Certain Supreme buses were equipped with RECARO Ergo-M commercial bus operator's seats that are subject to Johnson Controls Recall No. 15E088. According to Johnson Controls, certain "J-brackets" in the Ergo-M commercial bus operator's seats may be missing welds. As a result, the seatbelt anchorage assembly may separate from the J-bracket and the bus driver may not be properly restrained in the event of a crash. There have not been reports of accidents or injuries concerning this issue.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : According to Johnson Controls, if the J-Bracket is missing welds it may separate from the seatbelt anchorage assembly and increase the risk of injury in the event of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

By email dated Feb 27, 2016, Supreme Corporation was advised that Johnson Controls determined that certain RECARO Ergo-M commercial bus operator's seats contain a safety-related defect. Johnson Controls provided a list of serial numbers for equipment potentially affected by the condition. Supreme conducted a search of its records to identify vehicles equipped with the subject seats. As of May 2, 2016, Supreme has been able to identify 80 vehicles equipped with these seats. Supreme has not received any reports of accidents, injuries, or failures in Supreme vehicles related to the defect. On May 2, 2016 Supreme decided to conduct a recall to address the condition, based on the defect report from Johnson Controls.

Description of Remedy :

Description of Remedy Program : Owners will be advised to make an appointment with their local RECARO dealer to inspect and repair as needed at no charge (parts and labor) to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 19, 2016 - MAY 19, 2016

Planned Owner Notification Date : MAY 19, 2016 - JUL 08, 2016

* NR - Not Reported