

Part 573 Safety Recall Report**16V-299****Manufacturer Name :** Supreme Corporation**Submission Date :** MAY 10, 2016**NHTSA Recall No. :** 16V-299**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Supreme Corporation

Address : 2581 East Kercher Road
Goshen IN 46528

Company phone : 999

Population :

Number of potentially involved : 153

Estimated percentage with defect : NR

Vehicle Information :

Vehicle : 2007-2009 Supreme Silver Crown, Ponyxpress

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Descriptive Information: Recreational Vehicles equipped with Lippert Components Coachstep electric double or triple entrance steps that are subject to Lippert Components, Inc. Recall No 15E078

Production Dates : JAN 24, 2007 - JUN 30, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Certain Supreme buses were equipped with Coachstep electric double or triple entrance steps that are subject to Lippert Components, Inc. Recall No. 15E078. According to Lippert Components, a potential structural fracture of the center bolt of the fan gear assembly, which may cause the fan-gear assembly to disengage from the steps.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : According to Lippert Components, if the center bolt of the fan-gear assembly fractures, the fan-gear assembly may disengage from the entrance steps resulting in the steps becoming unstable, potentially resulting in a passenger fall and injury.

Description of the Cause : According to Lippert Components, the entrance step's center bolt of the fan-gear assembly may fracture due to stress on the bolt caused by misuse of the entrance steps, overloading, collision or other outside influences.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Lippert Components, Inc.

Address : P.O. Box 2888

Elkhart INDIANA 46515

Country : United States

Chronology :

In March 2016, Supreme's Quality Department learned that Lippert Components, Inc. had determined that certain Coachstep Electric Double and Triple steps contain a safety-related defect. Lippert Components provided a list of serial numbers for equipment potentially affected by the condition. Between March and April 2016, Supreme conducted a search of its records to identify vehicles equipped with the subject electric steps. As of May 2, 2016, Supreme has been able to identify and verify 153 vehicles equipped with these electric steps. Supreme has not received any reports of accidents, injuries, or failures in Supreme vehicles related to the defect.

On May 2, 2016 Supreme decided to conduct a recall to address the condition, based on the defect report from Lippert Components, Inc.

Description of Remedy :

Description of Remedy Program : Owners will be advised to make an appointment with their local Lippert Components dealer to inspect and repair as needed at no charge (parts and labor) to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 19, 2016 - MAY 19, 2016

Planned Owner Notification Date : MAY 19, 2016 - JUL 08, 2016

* NR - Not Reported