

Part 573 Safety Recall Report**16V-304**

Manufacturer Name : Jayco, Inc.
Submission Date : MAY 10, 2016
NHTSA Recall No. : 16V-304
Manufacturer Recall No. : 9901298

**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.
 Address : 903 South Main Street
 PO Box 460 Middlebury IN 46540
 Company phone : 800-283-8267

Population :

Number of potentially involved : 241
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Travel Trailer Jay Flight SLX
 Vehicle Type : TRAILERS
 Body Style :
 Power Train : NR
 Descriptive Information : G77A0290-0348 G77C0283-0333 G77D0247-0295 G77F0170-0185
 G77J0230-0353 ONLY UNITS PRODUCED IN IDAHO PLANT
 Production Dates : MAR 03, 2016 - APR 20, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Propane tank installed on the A frame is lacking lock washer on the bolts(2) that fasten the tank to the angle irons on the A-frame.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : With the lock washer missing, the Propane tank bolts may work loose from the angle irons and allow the tank to become loose and detached from the angle irons and fall from unit while being towed. Could cause accident with personal injury and/or property damage

Description of the Cause : A changed of vendor for the propane tank - called for change in type of bolt used and production did not continue past practice of adding the lock washer to the new bolts.

Identification of Any Warning that can Occur : tank not secure to A-frame - loose

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

May 4, 2016 Transport company contact Jayco production in Idaho regarding issue of loose propane tanks discovered while an unit was in transit to dealer. Idaho production immediately inspected all units on site and found specific run of units that the lock washer was omitted on the 2 bolts that secure the propane tank to the A-frame. - INDIANA production also audited production lines for the Jay Flight SLX and confirmed that the lock washer were being installed on the same product produced - All units on IDAHO site where repaired by adding the lock washer to secure the tank.

Description of Remedy :

Description of Remedy Program : Add Lock Washer to the 2 bolts that secure the tank to the A-frame. Jayco will provide a complete set of bolts, lock washers and nuts at no charge under the recall remedy - to cover any voids

How Remedy Component Differs from Recalled Component : presence of lock washer on 2 bolts that secure the tank to A-frame

Identify How/When Recall Condition was Corrected in Production : Production Group leaders are prepared to re-train line workers on the proper install of the propane tank to the A-frame prior to the next run of the Jay Flight SLX scheduled in IDAHO.

Recall Schedule :

Description of Recall Schedule : We are prepared to release the recall upon receipt of recall number. Most of the affected units are part of Dealers' inventory.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported