

Part 573 Safety Recall Report

16V-365

Manufacturer Name : Transportation Collaborative, Inc.

Submission Date : MAY 17, 2016

NHTSA Recall No. : 16V-365

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Transportation Collaborative, Inc.

Number of potentially involved : NR

Address : 7 Lake Station Road

Estimated percentage with defect : NR

Warwick NY 10990

Company phone : 845-988-0419

Vehicle Information :

Vehicle 1 : 2014-2016 Trans Tech Bus SST

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Student Safety Transporter with S-Series Lift

Production Dates : JAN 02, 2014 - JAN 01, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Under certain conditions present in some applications, the platforms included on the subject S-series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position, which, if left unchecked, can propagate to the point of separation where the rear portion of the pivot plate renders the lift potentially inoperable and possibly unsafe for the operator.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Platform can fall out of vehicle or fail during operation which can lead to serious injuries for both the operator and occupant if applicable.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Ricon

Address : 1135 Aviation Place
San Fernando CALIFORNIA 91340

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported