

Part 573 Safety Recall Report

16V-385

Manufacturer Name : Winnebago Industries, Inc**Submission Date :** MAY 26, 2016**NHTSA Recall No. :** 16V-385**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 306

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2015-2016 Winnebago Tour

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Affects certain Daimler Trucks with front axle assemblies by ZF

Production Dates : AUG 29, 2014 - NOV 04, 2015

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2 : 2015-2016 Itasca Ellipse

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Chassis built with certain front axle assemblies identified by ZF

Production Dates : AUG 29, 2014 - NOV 04, 2015

VIN Range 1 : Begin : NR End : NR Not sequential**Description of Defect :**

Description of the Defect : ZF reported "the steering box type 8018 as a subcomponent delivered from Bosch is mounted into a subframe including front axle (Independent Front Steering Axle). This subcomponent has its own part no allocated by Bosch. A wrong spacer from the steering box type 8016 was installed into the version 8018 and the insufficient height can result in too much play. The consequence will that within an undefined period, the connection will wear out." Reference ZF equipment recall submitted to NHTSA May 9, 2016.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : ZF reported " The defect could lead to a loss of mechanical connection between the steering wheel and the front axle wheels. This could lead to a loss of control of the vehicle." Reference ZF equipment recall submitted to NHTSA May 9.

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : ZF North America, Inc

Address : 15811 Central Drive
Northville, MI 48167

Country : NR

Chronology :

E-mail from Daimler on May 25, 2016 giving notice of their recall FL-712

Description of Remedy :

Description of Remedy Program : Steering gears will be inspected and suspect gears will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported