

Part 573 Safety Recall Report

16V-428

Manufacturer Name : East Manufacturing Corp.

Submission Date : JUN 06, 2016

NHTSA Recall No. : 16V-428

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : East Manufacturing Corp.

Address : 1871 State Route #44

P.O. BOX 277 Randolph OH 44265

Company phone : 330-325-9921

Population :

Number of potentially involved : 6

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2016 East Hybrid, Steel Dump

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : VIN tags were incorrectly populated. As a result, GAWRs and in some cases GVWRs were overstated.

Production Dates : MAY 16, 2016 - JUN 02, 2016

VIN Range 1 : Begin : 1E1D3M488HR058755 **End :** 1E1D3N584HR058756 Not sequential

VIN Range 2 : Begin : 1E1J9P380HR059239 **End :** 1E1J9P387HR059240 Not sequential

VIN Range 3 : Begin : 1E1D3M488HR059257 **End :** 1E1D3M488HR059257 Not sequential

VIN Range 4 : Begin : 1E1W4G48XHR057436 **End :** 1E1W4G48XHR057436 Not sequential

Description of Defect :

Description of the Defect : VIN tags were incorrectly populated

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Drivers may overload trailer based on VIN tag information

Description of the Cause : Errors made in the creation of the VIN tag.

Identification of Any Warning NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

A mistake was discovered on a VIN tag that was not yet installed on a trailer and we investigated all the VIN tags that the individual who made the error created. 6 errors were found in the database.

Description of Remedy :

Description of Remedy Program :	Supply a new VIN tag and drive rivets to the custodian of the trailer and provide instructions on how to change the tag. After receiving written confirmation that this has been done, East will pay out 1 hour of compensation to the custodian.
How Remedy Component Differs from Recalled Component :	The recalled component will be on the trailer or damaged as a result of removing it from the trailer. The new component will be sent to the custodian to replace the old component.
Identify How/When Recall Condition was Corrected in Production :	The error was discovered when a tire change was made to a trailer prompting a change to a VIN tag. As soon as the error was discovered it was corrected in production.

Recall Schedule :

Description of Recall Schedule :	As soon as NHTSA approves notifications we will send out the notifications.
Planned Dealer Notification Date :	JUL 04, 2016 - JUL 25, 2016
Planned Owner Notification Date :	JUL 04, 2016 - JUL 25, 2016

* NR - Not Reported